

#### Operating Policies and Procedures

# Outage Planning, Commissioning and Testing OPP 601

Issued: 2014-07-02 Supersedes: 2009-09-01

# 601 TRANSMISSION OUTAGES AND LIMIT CHANGES

### 3. Policy

#### 3.1 Outage coordination and reliability

• The legal owner of a transmission facility must provide, as soon as reasonable, unplanned derates of any of its transmission facilities and derate information, including the transmission facilities affected, time period, and cause of the derate. The legal owner of a transmission facility must subsequently inform the ISO of plans to restore the derated transmission facilities to their full rating.

#### 4.1 ISO

The ISO must:

• Coordinate delayed forced outage with legal owners to ensure acceptable system risks.

## 4.2 Legal Owner of a Transmission Facility

The legal owner of a transmission facility must:

- Provide schedules, in electronic form and in the format of <u>Appendix A</u>, to the ISO (e-mail address <u>mailto:outage.scheduling@aeso.ca</u>) as follows:
  - As soon as practical, provide unplanned derates of all transmission facilities to the ISO by telephone. The derate information must include elements affected, time period, and cause of the derate.

## 6. Revision History

Issued	Description
2014-07-02	Planned outage information transferred to new section 306.4 of the ISO rules, <i>Transmission Planned Outage Reporting and Coordination</i> ; and replaced the term "unplanned outage" with "delayed forced outage".
2009-09-01	Supersedes 2008-11-13
2008-11-13	Supersedes 2007-09-27
2007-09-27	Supersedes 2005-05-25; Generator Outage Coordination info transferred to new OPP 606
2005-05-25	Supersedes 2003-07-28
2003-07-28	Revised to ISO Operating Policies and Procedures

Issued: 2014-07-02 Page 1 of 1